


2007/3207 - 023202



**FIG. 1**

Pipetter Device 200




FIG. 2




FIG. 3

10073207.0221302




FIG. 4




FIG. 5

VENT 20° ZONE/OUT




FIG. 6




FIG. 7




FIG. 8




FIG. 9

1000

Air  
Pressure




FIG. 10

1100




FIG. 11

1200

1202  
Measure a First Air Pressure



1204  
Insert Pipette Tip



1206  
Measure a Second Air Pressure



Yes

1210

Non-Defective  
Tip

No

1212

Discard Defective  
Pipette Tip

FIG. 12

1300




FIG. 13